



---

# CanSat 2023

## Post Flight Review (PFR)

### *Version 1.0*

**1070**  
**Obsidian**




# Presentation Outline



Number	Contents	Presenter(s)	Slide No.
1	Introduction	Emily Jolly	1
2	System Overview	Adam Burden	4
3	Concept of Operations & Sequence of Events	Preston Beesley	13
4	Flight Data Analysis	John Raburn	18
5	Failure Analysis	Brooks Calhoun	29
6	Lessons Learned	Jamie Roberson & Emily Jolly	32



# Team Organization





---

# System Overview

**Adam Burden**




# Payload Design Description (1/6)




**ACTUAL**

**CAD MODEL**





# Payload Design Description (2/6)



Our payload has a four-panel heat shield and uprighting system and a two-segment flagpole.





# Payload Design Description (3/6)



**ACTUAL**

**CAD MODEL**



Servo


Nylon Threaded Rod

Stemnut

Panel Hinge



# Payload Design Description (4/6)



The Stemnut is operated by the servo causing the panels to move up and down.





# Payload Design Description (5/6)



**ACTUAL**



**CAD MODEL**

Flagpole Servo

Release Latch

Camera Facing Down

The release mechanism is operated by a servo under the Top Plate.






# Payload Design Description (6/6)



## ACTUAL

Flag Servo rotates 180 degrees from downward position to upward position while counter weight keeps extension point nadar towards the sky.




Broken Flagpole

## CAD MODEL

Flagpole Section Two

Hinge with Counterweight

Flagpole Section One





# Container Design Description (1/2)



**ACTUAL**

**CAD MODEL**



TPU Holding Plate



Fiberglass Container Shell

The Holding plate is attached to the container by screws and nuts.

The container is attached to the payload by holding plate is inserted into the top baseplate and held by a servo head.





# Container Design Description (2/2)



**ACTUAL**

**CAD MODEL**

TPU holding plate slots into releasing mechanism in manner shown.



TPU Holding Plate

Top Plate

Release Latch



---

# Concept of Operations & Sequence of Events


**Preston Beesley**



# Planned & Actual CONOPS (1/3)



## Planned CONOPS






# Planned & Actual CONOPS (2/3)



## Actual CONOPS





# Planned & Actual CONOPS (3/3)



Operation	Planned	Actual	Reasoning
Ascending	CanSat is launched inside rocket	YES	Visual launch
	Ground Station continues receiving telemetry	YES	Received throughout
Descending	CanSat is released from rocket at apogee	YES	Released at apogee of 632 m
	CanSat descends at 15 m/s	YES	Descended at 15.45 m/s
	Container is released at 500 m	YES	Visual deployment
	CanSat descends from 500 to 200 m at 20 m/s	YES	Descended at 19.52 m/s
	Payload Parachute is deployed at 200 m	YES	Visual deployment
	CanSat descends from 200 to 0 m at 5 m/s	NO	Descended at 8.7 m/s
Landed	CanSat uprights	NO	Lost Power
	Flag is raised	NO	
	Audio beacon triggers	NO	





# Planned & Actual SoE



Mission Timeline	Planned	Actual
Pre-Launch	Ground Station Setup	YES
	Prepare CanSat for launch	YES
	CanSat Check-In	YES
Launch	Turn CanSat on	YES
	Integrate CanSat with Rocket	YES
	Monitor Ground Station	YES
	Move to Launch Control Table & Execute Launch	YES
Descent	Monitor Ground Station	YES
Recovery	Recover the CanSat	YES
Data Analysis	Analyse Data	YES
	Turn in Thumb Drive	YES



---

# Flight Data Analysis


**John Raburn**



# Payload Altitude Plot (1/4)



### Relative Altitude of Payload



Point of Interest	Value (m)
Ascending	79.6
Descending	631.8
Container Release	495.1
Parachute Deployed	194.0
Power Loss	40.4


The rocket did not reach the expected height of 670 - 725m. The apogee achieved was 632m.



# Payload Altitude Plot (2/4)



## Calculated Acceleration of Payload After Container Release




The combination of the payload releasing from the container and the heat shield deploying helped decelerate the CanSat from its downward fall.



# Payload Altitude Plot (3/4)



## Calculated Acceleration of Payload After Parachute Release




The parachute releasing did cause the payload to decelerate, but not as much as expected which should have been 5 m/s.



# Payload Altitude Plot (4/4)



## Velocity of Payload




Point of Interest	Velocity
Descending	15.45
Container Release	19.52
Parachute Release	8.7



# Payload Temperature Plot



## Temperature Reading of Payload



Point of Interest	Value
High	35.2
Low	29.5


The temperature inside the rocket reached up to 35.2 °C before releasing from the rocket and decreasing to 29.5 °C



# Payload Battery Voltage Plot




## Battery Voltage of Payload








# Payload GPS Position Plot (1/2)





# Payload GPS Position Plot (2/2)



This is the descent of the Payload, which shows it drifting down to the ground

This is the GPS while the rocket was ascending


During the ascent, the SIV count dropped from 15 to 3, meaning that the GPS altitude data could not properly update until it was released from the rocket.




# Payload Tilt Sensor Plot



### Tilt Sensor X Position of Payload



### Tilt Sensor Y Position of Payload





# Payload Camera Video



## Payload Camera Video

[https://www.youtube.com/watch?v=QB1ejdPzqbc&ab\\_channel=JohnRaburn](https://www.youtube.com/watch?v=QB1ejdPzqbc&ab_channel=JohnRaburn)

Due to inopportune circumstances, our last working camera was missing the blue and green color receptors, resulting in the above video recording in only pink tones



---

# Failure Analysis

**Brooks Calhoun**



# Overview



Description of Failure	Cause of Failure	Corrective Action
<b>Ground station overheating</b>	Lack of fans & shade	Changing GCS computer & heading under a tent for shade
<b>Flag raising mechanism broke</b>	Broke on impact with ground	Strengthen the parts of the flag
<b>Batteries shorted mid flight</b>	Improper insulation from carbon fiber rods	More application of electrical tape or redesign placement of batteries
<b>Heatshield did not operate for uprighting</b>	The batteries shorted	Secure connections and disconnections between power sources
<b>buzEnable did not enable the buzzer</b>	Server required flight or sim mode active in order to receive command	Altered code to allow for change at any point in instruction
<b>Camera start was unreliable</b>	Electrical hardware malfunction	Invest in more reliable hardware that require less maintenance




# Failure Analysis



## Main Failure

After researching into the graphs and physical data, we discovered that our CanSat failed its landing phase because of power surges. During our ascent and landing phases, arcs were observed crossing through the carbon fiber rods into the PCB, which caused a black-out. The only exception was the camera itself, as it was connected to a carbon fiber rod that was grounded to the power system. This caused the camera to continue working while the rest of the electronics were non-functional.

In the future, we will be more careful and do more research into the materials that we use along with their properties, as this can become a critical failure point later on.





---

# Lessons Learned

**Jamie Roberson and Emily Jolly**





# Accomplishments



Electrical	Mechanical	Software
<ul style="list-style-type: none"><li>● PCB held up under stresses and impact allowing for successful data collection</li><li>● All components remained in mounted position during flight</li><li>● Successfully created an effective power budget for the mission</li></ul>	<ul style="list-style-type: none"><li>● Container parachute slowed payload down to desired 15 m/s.</li><li>● Heatshield deployed and slowed the payload down to approximately 20 m/s.</li><li>● Second parachute deployed..</li><li>● Structure remained intact and functional.</li></ul>	<ul style="list-style-type: none"><li>● The GCS was able to effectively monitor and control the CanSat.</li><li>● The GCS was optimized so that it could properly receive the telemetry and graph without lagging.</li><li>● The GCS effectively used a doubly linked list as an enqueueing system for packets.</li><li>● The embedded systems were efficient and reliable.</li></ul>



# Failures



Electrical	Mechanical	Software
<ul style="list-style-type: none"><li>• Multiple issues with battery containment theoretically causing a power blink</li><li>• Mounting components were complicated</li></ul>	<ul style="list-style-type: none"><li>• Carbon fiber rods are conductive</li><li>• The flag raising mechanism broke on impact</li><li>• Middle plate fractured but did not fail</li></ul>	<ul style="list-style-type: none"><li>• Some commands were unnecessary and not optimized correctly.</li><li>• Some systems had strange timings or were difficult to work with based on their implementation (ie. the buzzer).</li></ul>



# Conclusion



CANSAT TEAM 1070	
	Better communication between sub-teams in the early stage of mission development would have allowed for more success in the late stage of the mission.
	Learned invaluable work experience relevant to desired engineering industry.
	Although a perfect launch was ideal, it did not have to be and this was a wonderful learning experience.
	We learned to put more focus on safety and reliability. More time could have been spent ensuring these factors.