



CanSat 2023 Post Flight Review (PFR)

Team 1082 PWr Aerospace





Introduction


Tobiasz Puślecki



Section	Presenter
Introduction	Tobiasz Puślecki
Systems Overview	Konrad Łebek
Concept of Operations and Sequence of Events	Hubert Kulik
Flight Data Analysis	Hubert Kulik
Failure Analysis	Hubert Kulik
Lessons Learned	Tobiasz Puślecki












System Overview

Konrad Łebek
















































Container Major Parts and Components













Concept of Operations and Sequence of Events


Hubert Kulik





Stage	Activities
Pre-launch activities	 Arrival at launch site CanSat preparations CanSat assembly and weighing Turning CanSat for official inspection
Launch	 Setting ground station at designated place Placing CanSat in rocket compartment Execution of launch sequence USB stick delivery to judges
Recovery and further actions	 CanSat probe recovery Data gathering and presentation preparing










Planned Sequence of Events	Actual
Place CanSat in the rocket	Success
Take the rocket to the launch site	Success
Power on the ground station (GS)	Success
Send calibration commands from GS to container	Success
Launch sequence execution	Success
Deployment from rocket (~700m)	Success
Descending using the first parachute at a rate of 15 m/s (+/- 5ms)	Success
Deployment of payload (~500m)	Success
Heatshield opening, descending at a rate of 20 m/s or less	Success
Deployment of second parachute, slow down to 5 m/s (~200m)	Partially
Touchdown, upright, rise a flag, stopping telemetry	Partially
Recovery of CanSat with working buzzer	Partially
Gathering microSD card from CanSat	Success





Flight Data Analysis


Hubert Kulik



<u>Altitude was calculated using data from pressure sensor.</u> Further analysis will be performed using data from Payload sd card. We have received 90 out of 103 sent packets.


















GPS Satellites























We noticed aliasing. Details will be provided in the following slide





CanSat 2023 Payload Camera Events Summary

Team: 1082 – PWr Aerospace





CanSat 2023

Bonus Camera Recording

Team 1082 - PWr Aerospace






Failure Analysis

Hubert Kulik





Failure	Root Cause	Corrective actions
Uprighting mechanism failed	Uprighting leg collapsed under the stress of the landing. Caused by the high latteral speed due to wind.	Proper materials used F.E. aluminium instead of 3D printed ASA. Higher safety margins for unexpected environmental factors.
Payload parachute descents speed was to low	No testing of the parachute descent speed was done before the launch.	The parachute should be tested with the proper weight before launch.
Some packets were lost	Not enough motor EMI shielding, probably hand-held radio (460MHz) second harmonic interference with XBee radio (915MHz). Line-of-sight was broken by the launchpad geometry	Changing one of the radios frequency. Better EMI management (shorter cables, shielding, keeping the distance)







Lessons Learned

Tobiasz Puślecki





What worked?

We found our payload and container

Ground station sent calibration command and received telemetry

Packet transmission frequency met requirements

Plotting worked properly

What didn't work?

We lost 13 packets

Slower than expected descent

Upright mechanism didn't work







- Amazing adventure!
- Sim mode is necessary ⁽²⁾
- Nice to see you again!
- We know how to work in team project!

